PROCEDURES – ONGOING MAINTENANCE

DETAILS OF INSPECTION VIOLATIONS CORRECTIVE ACTION STATEMENT

NO.	LOCATION	REF.	POINTS	CRITICAL DESCRIPTION
1	POTABLE WATER	05	0	Yes
	REE RESIDUAL HALOGEN AT THE DISTRIBUTION FAR POINT MEASURED BY T	HE ENGI	NEER'S TEST	KIT AND THE INSPECTOR'S
TEST SHOV 1.90 F	VED A DISCREPANCY OF 0.39 PPM. THE INSPECTOR'S TEST KIT MEASURED 1.	.51 PPM	AND THE ENC	GINEER'S TEST KIT MEASURED
	METERS ONBOARD HAVE NOW BEEN RE-CALIBRATED WITH MAKER'S	SINSTR	UCTIONS.	
2	POTABLE WATER	80	0	No
DIFFE NOT F	BACKFLOW PREVENTION DEVICES REQUIRING TESTING HAD BEEN TESTED OF FRENCES WERE RECORDED. ORDING OF THE PRESSURE DIFFERENCES HAVE NOW BEEN INCORP		·	
SYST		00	0	V
3	POTABLE WATER	03	0	Yes
PROD WATE TECH	/IEW OF THE POTABLE WATER PRODUCTION RECORDS SHOWED THAT FOR S JUCTION IR WAS NOT CHLORINATE TO AT LEAST 2.0 PPM. IT WAS STATED BY THE STA NICAL			
	R, BUT THIS WAS NOT DOCUMENTED IN THE LOG BOOK. W COLUMN HAS BEEN ADDED TO THE LOGBOOK FOR THIS PURPOSE	E AND S	TAFF INSTR	RUCTED
4	DECK PANTRY - MAIN DECK MIDSHIP	21	1	No
TWO	HOLES WERE NOTED IN THE COUNTER NEXT TO THE COFFEE MAKER.			
HOLE	ES HAVE BEEN SEALED			
5	DECK PANTRIES	20	2	No
THE V	VATER WARMERS USED FOR TEA WERE LABELED "FOR HOUSEHOLD USE ON	LY".		
	SUCH WATER WARMERS HAVE BEEN REMOVED FROM PANTRIES. ST. HINES FOR HEATING WATER.	AFF INS	STRUCTED T	O USE THE COFFEE
6	BALLROOM BAR	36	0	No
THE L	IGHTS OVER THE BAR COUNTER WERE NOT SHIELDED OR SHATTER-RESISTA	ANT.		
ALL L	IGHTS HAVE NOW BEEN FITTED WITH SHATTER-RESISTANT BULBS.			
7	PROVISIONS - DRY STORES	15	0	Yes
A FEV	V DENTED CANS WERE NOTED IN THIS AREA.			
ALL (CANS CHECKED AND THE DENTED ONES REMOVED. STAFF INSTRUC	TED		
8	FOOD SERVICE GENERAL	33	0	No
	DECKHEADS AND BULKHEADS WERE DIFFICULT TO CLEAN DUE TO GAPS, OPE PMENT.	ENINGS,	LOOSE PROF	ILE STRIPS, AND ATTACHE
STAF	WAS NOTED IN THE MAIN GALLEY, CREW GALLEY, AND PROVISIONS. FF INSTRUCTED AND REMINDED TO REPORT SUCH DEFECTS TO THE CEDURES –ONGOING MAINTENANCE	MAINT	ENANCE ST	AFF USING THE ESTABLISHED
9	FOOD SERVICE GENERAL	33	1	No
THE C	DECK TILES WERE CRACKED, SHIPPED, AND TOTHERWISE DAMAGED THROUG	SHTOUT	THE GALLEY	AND CREW GALLEY.
	F INSTRUCTED AND REMINDED TO REPORT SUCH DEFECTS TO THE CEDURES – ONGOING MAINTENANCE	MAINT	ENANCE STA	AFF USING THE ESTABLISHED
10	FOOD SERVICE GENERAL	21	1	No
THE N	ION-FOOD CONTACT SURFACES OF EQUIPMENT WERE DIFFICULT TO CLEAN	DUE TO	GAPS AND O	PEN SEAMS.
STAF	E INSTRUCTED AND REMINDED TO REPORT SUCH DEFECTS TO THE	MAINT	ENANCE ST	AFE USING THE ESTABLISHED

THE FOOD CONTACT SURFACES OF EQUIPMENT WERE DIFFICULT TO CLEAN DUE TO GAPS, WIRES, FAN COILS, AND OTHER FEATURES. STAFF INSTRUCTED AND REMINDED TO REPORT SUCH DEFECTS TO THE MAINTENANCE STAFF USING THE ESTABLISHED PROCEDURES - ONGOING MAINTENANCE. 12 PASTRY 20 2 No FREEZER #47 HAD BEEN OUT OF ORDER FOR MORE THAN A WEEK. REPLACEMENT OF REFRIGERATION PIPEWORK IN THIS AREA. 13 MAIN GALLEY - DISHWASH 22 0 No THE FINAL RINSE HAD AN ERRATIC SPRAY PATTERN AND THE LEFT NOZZLE WAS CLOGGED. THIS NOZZLE HAS BEEN REMOVED AND CLEANED AND IS NOW WORKING CORRECTLY. STAFF INSTRUCTED TO INSPECT THESE NOZZLES ON A REGULAR BASIS AND REPORT ANY DEFECTS FOUND. HOT GALLEY No THE AREA BETWEEN AND UNDER THE HOT PLATES WERE ENCRUSTED WITH AN OLD FOOD RESIDUE.

20

2

Nο

A DEEP CLEANING PROGRAMME HAS BEEN RE-ESTABLISHED

11 FOOD SERVICE GENERAL

15 **PROVISIONS - FREEZER STORAGE** 19 0 No

TWO CONTAINERS WERE OPEN WHILE STORED IN THE FREEZER ROOMS.

ALL CONTAINERS NOW CLOSED AND STAFF INSTRUCTION HAS TAKEN PLACE